

dbraun99 LLC SU Carburetor Refurbishing Pricing

Type	Refurbishing Price per pair	Throttle Replacement Price with Refurbishing-per pair (x1.5 for triple)	Throttle Replacement Price as standalone service-per pair (x1.5 for triple)
H Type (MG "T" series, MGA, TR3, etc.)	\$515 a pair \$775 a triple	\$155 for replacement of std. throttle shafts and bushings	\$200 for replacement of std. throttle shafts and bushings
HS Type (MGB, MG Midget, TR4 A, Volvo etc.)	\$490 a pair \$740 a triple	\$145 for replacement of std. throttle shafts and bushings	\$185 for replacement of std. throttle shafts and bushings
HIF Type (MGB, Volvo etc.)	\$490 a pair \$740 a triple	\$145 for replacement of std. throttle shafts and bushings	\$185 for replacement of std. throttle shafts and bushings
HD Type (Jaguar, Big Healy, etc.)	\$540 a pair \$815 a triple	\$155 for replacement of std. throttle shafts and bushings	\$200 for replacement of std. throttle shafts and bushings
HD Type with Enrichment Carburetor	\$590 a pair \$885 a triple	\$155 for replacement of std. throttle shafts and bushings	\$200 for replacement of std. throttle shafts and bushings

Included in the price of the refurbishing is:

- polishing and mechanical sealing of aluminum surfaces
- jets
- metering needles
- float needles
- plating of the steel hardware in zinc (silver, nickel or Black zinc depending upon application)

Included in the price of the throttle replacement is:

- new bushings
- new shafts with belcranks installed

Refurbishing cost does not include cost of new floats; throttle disks; or replacement of parts rendered inoperable by previous attempts at rebuilding or corrosion. On carbs that have poppet-style emissions throttle disks, we will replace those with solid disks unless you indicate otherwise.

I will call you with a quote for these issues.

- Pricing for oversize shafts in lieu of standard shafts on HS carburetors deduct 15% from pricing shown above.
- Note: Return Shipping is included in pricing.

May 1, 2020

<http://www.dbraun99.com>
dave@dbraun99.com